

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BRS	L1	6856	cotter nearl pin	USPA T; EPO; JPO; DERW ENT	2004/09/2 1 17:49			0
2	BRS	L3	97	12 and flexible	USPA T; EPO; JPO; DERW ENT	2004/09/2 1 16:55			0
3	BRS	L4	0	13 and ladder	USPA T; EPO; JPO; DERW ENT	2004/09/2 1 16:55			0
4	BRS	L5	6	12 and ladder	USPA T; EPO; JPO; DERW ENT	2004/09/2 1 16:55			0
5	BRS	L2	321	11 and (403/\$.ccls. or 24/\$.ccls.)	USPA T; EPO; JPO; DERW ENT	2004/09/2 1 17:38			0
6	IS&R	L6	255	((24/706) or (24/706.2) or (24/706.3)).CCLS.	USPA T; EPO; JPO; DERW ENT	2004/09/2 1 17:15			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
7	IS&R	L7	148	(411/513).CCLS.	USPA T; EPO; JPO; DERW ENT	2004/09/2 1 17:15			0
8	BRS	L8	210	11 and (411/\$.ccls.)	USPA T; EPO; JPO; DERW ENT	2004/09/2 1 17:16			0
9	BRS	L9	486	11 and (403/\$.ccls. or 24/\$.ccls. or 411/\$.ccls.)	USPA T; EPO; JPO; DERW ENT	2004/09/2 1 17:50			0
10	BRS	L10	276	19 not 18	USPA T; EPO; JPO; DERW ENT	2004/09/2 1 17:39			0
11	BRS	L11	276	110 not 16	USPA T; EPO; JPO; DERW ENT	2004/09/2 1 17:39			0
12	BRS	L12	34280	(cotter or pin) and clip	USPA T; EPO; JPO; DERW ENT	2004/09/2 1 17:49			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
13	BRS	L13	3881	l12 and chain	USPA T; EPO; JPO; DERW ENT	2004/09/2 1 17:49			0
14	BRS	L14	207	l13 and (403/\$.cccls. or 24/\$.cccls. or 411/\$.cccls.)	USPA T; EPO; JPO; DERW ENT	2004/09/2 1 17:50			0
15	BRS	L15	197	l14 not l11	USPA T; EPO; JPO; DERW ENT	2004/09/2 1 17:50			0